

20458.



TEST REPORT

NUMBER : TWNC00102640

APPLICANT: SHINE SPORT FACILITY CO., LTD.
27 GONG HUAN RD.
AN NAN DIST TAINAN TAIWAN

DATE : JAN 16, 2009

SAMPLE DESCRIPTION:

ONE (1) SETS OF SUBMITTED SAMPLE SAID TO BE :
ITEM NAME : TOSSERS BEANBAGS
QUANTITY : 1 SET
VENDOR/MANUFACTURER
COUNTRY OF ORIGIN
DATE SAMPLE RECEIVED : DEC 29, 2008
DATE TEST STARTED : DEC 30, 2008

TEST CONDUCTED:

AS REQUESTED BY THE APPLICANT, FOR DETAILS PLEASE REFER TO ATTACHED PAGES.

CONCLUSION:

TESTED SAMPLE	STANDARD	RESULT
TESTED COMPONENTS OF SUBMITTED SAMPLES	TOTAL LEAD (Pb) CONTENT IN SURFACE COATING - AS PER U.S. CONSUMER PRODUCT SAFETY IMPROVEMENT ACT 2008 (H.R. 4040) TITLE I, SECTION 101	NOT APPLICABLE (SEE NOTE)
	TOTAL LEAD (Pb) CONTENT IN SUBSTRATE MATERIAL - AS PER U.S. CONSUMER PRODUCT SAFETY IMPROVEMENT ACT 2008 (H.R. 4040) TITLE I, SECTION 101	PASS

NOTE: NO HEAVY METAL CONTENT TEST IS CONDUCTED DUE TO NO SURFACE COATING.

AUTHORIZED BY:
ON BEHALF OF INTERTEK TESTING SERVICES
TAIWAN LIMITED



K. Y. LIANG
DIRECTOR

THIS REPORT SHALL NOT BE REPRODUCED
EXCEPT IN FULL, WITHOUT THE WRITTEN
APPROVAL OF THE LABORATORY.



NUMBER: TWNC00102640

TEST CONDUCTED

TOTAL LEAD (Pb) CONTENT IN SUBSTRATE MATERIAL

AS PER U.S. CONSUMER PRODUCT SAFETY IMPROVEMENT ACT 2008 (H.R. 4040), TITLE I, SECTION 101 FOR CHILDREN'S PRODUCTS CONTAINING LEAD, ACID DIGESTION METHOD WAS USED AND TOTAL LEAD CONTENT WAS DETERMINED BY INDUCTIVELY COUPLED ARGON PLASMA SPECTROMETRY.

<u>TESTED COMPONENT</u>	<u>RESULT (ppm)</u>
(1) (#1)	<5
(2) (#1)	<5
(3) (#1)	<5
(4) (#1)	<5
(5)	<5
(6)	<5
(7) (#2)	<5
(8) (#2)	<5
(9) (#2)	<5
(10) (#2)	<5
(11) (#2)	<5
(12) (#2)	<5
(13) (#3)	11
(14) (#4)	<5
(15) (#4)	<5
(16) (#4)	<5
(17) (#4)	<5
(18) (#4)	<5
(19) (#4)	<5

LIMIT:

600 ppm AFTER FEB 10, 2009

300 ppm AFTER AUG 14, 2009

100 ppm AFTER AUG 14, 2011

REMARKS : ppm = PARTS PER MILLION = mg/kg

< = LESS THAN

#1 = RESULTS WERE TRANSFERRED FROM REPORT NO. TWNC00102626 DATED JAN 07, 2009

#2 = RESULTS WERE TRANSFERRED FROM REPORT NO. TWNC00102632 DATED JAN 07, 2009

#3 = RESULTS WERE TRANSFERRED FROM REPORT NO. TWNC00102638 DATED JAN 07, 2009

#4 = RESULTS WERE TRANSFERRED FROM REPORT NO. TWNC00102637 DATED JAN 16, 2009

Intertek Testing Services Taiwan Ltd.

8/F., No. 423, Ruiguang Road, Neihu District, Taipei 114, Taiwan, R.O.C.

全國公證檢驗股份有限公司

114 台北市內湖區瑞光路 423 號 8 樓


Tel: (+886-2) 6602-2888 2797-8885 Fax: (+886-2) 6602-2410



NUMBER: TWNC00102640

TEST CONDUCTED

PHOTO



PAGE 4 OF 4